

THE YEAR IN REVIEW EMR & CODR REPORTS

FY-2000

Type of Mishap	Cause of Mishap	Total
DETONATION	DESIGN DEFICIENCY	260
	MATERIAL FAILURE	
	PERSONNEL ERROR	
INDUCED DEFECT	ENVIRONMENT	217
	MATERIAL FAILURE	
	PERSONNEL ERROR	
MALFUNCTION	DESIGN DEFICIENCY	729
	MATERIAL FAILURE	
	PERSONNEL ERROR	
OBSERVED DEFECT	DESIGN DEFICIENCY	589
	ENVIRONMENT	
	MATERIAL FAILURE	
	PERSONNEL ERROR	
		1795

